

Work Order ID 128580

128580

Page 1

Item ID: D2278

Accept

N900040100

Setup Start ***NS1***

Revision ID:

Stop ***NS2***

Item Name: Step Leg

Start Date: 1/19/15 Start Qty: 10.00

10

Cust Item ID:

Required Date: 1/19/15 Req'd Qty: 10.00

10

Customer:

Reference: scrap - holes do not line up

Approvals:

Process Plan:

Date:

Tooling:

Date:

Run Start ***NR1***

QC:

Date:

SPC (Y/N):

Date:

Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr

Revision Nbr

D2278

Rev F

105

0.00

105

Small Fab

Memo

0.00

Small Fab

8 PULL FROM STK:
10-X D2278 B121845
SCRAP/DESTROY
HOLES DO NOT LINE UP

⑧ 15-01-19 PD

160

QC21- Final Inspection - Work Order Release

0.00

160

QC

Memo

0.00

Quality Control

15/1/19

SCRAP
15-1-19

Picklist Print

January-19-15 1:03:44 PM

Page 1

Work Order ID: 128580

128580

Parent Item: D2278

D2278

Parent Item Name: Step Leg

Start Date: 1/19/15

Required Date: 1/19/15

Start Qty: 10.00

Required Qty: 10.00

Comments: IPP Rev:A New Issue 05-11-07 JLM
IPP Rev:B Now 6061-T6 06-06-23 JLM
IPP Rev C New flat pattern 08.01.11 EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D2278		Manufactured	No				Each	23.0000		10			

D2278

Step Leg

15-01-18 PD

Location

Loc Qty

Loc Code

GA

23

106213

5

117871

6

121845

12

8